

feature, the regression adjustment procedure has many possible applications in chemical and process plants where there are often cascade processes with several inputs but only a few outputs, and where many of the variables are highly autocorrelated.

## 10-6 CONTROL CHARTS FOR MONITORING VARIABILITY

Just as it is important to monitor the process mean vector  $\mu$  in the multivariate case, it is also important to monitor process variability. Process variability is summarized by the  $p \times p$  covariance matrix  $\Sigma$ . The main diagonal elements of this matrix are the variances of the individual process variables, and the off-diagonal elements are the covariances. Alt (1985) gives a nice introduction to the problem and presents two useful procedures.

The first procedure is a direct extension of the univariate  $s^2$  control chart. The procedure is equivalent to repeated tests of significance of the hypothesis that the process covariance matrix is equal to a particular matrix of constants  $\Sigma$ . If this approach is used, the statistic plotted on the control chart for the  $i$ th sample is

$$W_i = -pn + pn \ln(n) - n \ln(|\mathbf{A}_i|/|\Sigma|) + \text{tr}(\Sigma^{-1} \mathbf{A}_i) \quad (10-34)$$

where  $\mathbf{A}_i = (n-1)\mathbf{S}_i$ ,  $\mathbf{S}_i$  is the sample covariance matrix for sample  $i$ , and  $\text{tr}$  is the trace operator. (The trace of a matrix is the sum of the main diagonal elements.) If the value of  $W_i$  plots above the upper control limit  $\text{UCL} = \chi^2_{\alpha, p(p+1)/2}$ , the process is out of control.

The second approach is based on the sample *generalized* variance,  $|\mathbf{S}|$ . This statistic, which is the determinant of the sample covariance matrix, is a widely used measure of multivariate dispersion. Montgomery and Wadsworth (1972) used an asymptotic normal approximation to develop a control chart for  $|\mathbf{S}|$ . Another method would be to use the mean and variance of  $|\mathbf{S}|$ —that is,  $E(|\mathbf{S}|)$  and  $V(|\mathbf{S}|)$ —and the property that most of the probability distribution of  $|\mathbf{S}|$  is contained in the interval  $E|\mathbf{S}| \pm 3\sqrt{V(|\mathbf{S}|)}$ . It can be shown that

$$E(|\mathbf{S}|) = b_1 |\Sigma| \quad (10-35)$$

and

$$V(|\mathbf{S}|) = b_2 |\Sigma|^2$$

where

$$b_1 = \frac{1}{(n-1)^p} \prod_{i=1}^p (n-i)$$

and

$$b_2 = \frac{1}{(n-1)^{2p}} \prod_{i=1}^p (n-i) \left[ \prod_{j=1}^p (n-j+2) - \prod_{j=1}^p (n-j) \right]$$

Therefore, the parameters of the control chart for  $|\mathbf{S}|$  would be

$$\begin{aligned} \text{UCL} &= |\Sigma| (b_1 + 3b_2^{1/2}) \\ \text{CL} &= b_1 |\Sigma| \\ \text{LCL} &= |\Sigma| (b_1 - 3b_2^{1/2}) \end{aligned} \quad (10-36)$$


The lower control limit in equation 10-36 is replaced with zero if the calculated value is less than zero.

Usually, in practice  $\Sigma$  will be estimated by a sample covariance matrix  $\mathbf{S}$ , based on the analysis of preliminary samples. If this is the case, we should replace  $|\Sigma|$  in equation 10-36 by  $|\mathbf{S}|/b_1$ , since equation 10-35 has shown that  $|\mathbf{S}|/b_1$  is an unbiased estimator of  $|\Sigma|$ .

#### ..... EXAMPLE 10-2 .....

To illustrate controlling process variability in the multivariate case, we will return to Example 10-1 and construct a control chart for the generalized variance. Based on the 20 preliminary samples in Table 10-1, the sample covariance matrix is

$$\mathbf{S} = \begin{bmatrix} 1.23 & 0.79 \\ 0.79 & 0.83 \end{bmatrix}$$



**Figure 10-13** A control chart for the sample generalized variance, Example 10-2.

so

$$|S| = 0.3968$$

The constants  $b_1$  and  $b_2$  are (recall that  $n = 10$ )

$$b_1 = \frac{1}{81}(9)(8) = 0.8889$$

$$b_2 = \frac{1}{6561}(9)(8)[(11)(10) - (9)(8)] = 0.4170$$

Therefore, replacing  $|\Sigma|$  in equation 10-36 by  $|S|/b_1 = 0.3968/0.8889 = 0.4464$ , we find that the control chart parameters are

$$UCL = (|S|/b_1)(b_1 + 3b_2^{1/2}) = 0.4464[0.8889 + 3(0.4170)^{1/2}] = 1.26$$

$$CL = |S| = 0.3968$$

$$LCL = (|S|/b_1)(b_1 - 3b_2^{1/2}) = 0.4464[0.8889 - 3(0.4170)^{1/2}] = -0.47 = 0$$

Figure 10-13 presents the control chart. The values of  $|S_i|$  for each sample are shown in the last column of panel (c) of Table 10-1.

Although the sample generalized variance is a widely used measure of multivariate dispersion, remember that it is a relatively simplistic scalar representation of a complex multivariable problem, and it is easy to be fooled if all we look at is  $|S|$ . For example, consider the three covariance matrices:

$$S_1 = \begin{bmatrix} 1 & 0 \\ 0 & 1 \end{bmatrix}, S_2 = \begin{bmatrix} 2.32 & 0.40 \\ 0.40 & 0.50 \end{bmatrix}, \text{ and } S_3 = \begin{bmatrix} 1.68 & -0.40 \\ -0.40 & 0.50 \end{bmatrix}$$

Now  $|S_1| = |S_2| = |S_3| = 1$ , yet the three matrices convey considerably different information about process variability and the correlation between the two variables. It is probably a good idea to use univariate control charts for variability in conjunction with the control chart for  $|S|$ .

## 10-7 LATENT STRUCTURE METHODS

Conventional multivariate control-charting procedures are reasonably effective as long as  $p$  (the number of process variables to be monitored) is not very large. However, as  $p$  increases, the average run-length performance to detect a specified shift in the mean of these variables for multivariate control charts also increases, because the shift is "diluted" in the  $p$ -dimensional space of the process variables. To illustrate this, consider the ARLs of the MEWMA control chart in Table 10-3. Suppose we choose  $\lambda = 0.1$  and the magnitude